




Mounting specifications


◆ **Recommendable reflow soldering**



● **Soldering with a soldering iron**

Tip of a soldering iron : 350 °C max (TQC / TDC / TQS / TQT series : 400 °C max.)
 Working time : 3 sec. max. (TQC / TQS / TQT series : 5 sec. max.)
 (Do not let the tip of soldering iron touch the POSCAP itself. Do not subject the POSCAP itself to excessive stress when soldering)

Land pattern



Unit : mm

Size code	a	b	c
B1, B1S, B2, B2S	1.6	2.7	1.4
D15, D2E, D2, D3L, D4	2.4	2.9	3.7
D15S	1.4 / 1.7 ^{*1}	2.6	4.6
D2S	1.4	2.6	5.1

*1 : +side / -side